

# Full Voltage Starters

---

## Types

- 3 Phase
- 50HP - 1000HP
- Non-Combination
- Combination Circuit Breaker
- Combination Fusible or Non-Fusible

## Options

- P/Bs, P/Ls, Transformers, etc
- Enclosures: NEMA 1, 3R, 12, 4, and 4X
- Voltages: 208, 230, 460, 575 Volt

[View Full Voltage Starter Catalog](#)

